



**DigSILENT Technical
Documentation**

PowerFactory V14.1 Release Notes



DIGSILENT GmbH
Heinrich-Hertz-Strasse 9
D-72810 Gomaringen
Tel.: +49 7072 9168 - 0
Fax: +49 7072 9168- 88
<http://www.digsilent.de>
e-mail: mail@digsilent.de

PowerFactory V14.1
Release Notes

Published by
DIGSILENT GmbH, Germany

Copyright 2011. All rights reserved. Unauthorised copying or publishing of this or any part of this document is prohibited.

December 6, 2011

Revision History

Version	Release	Description
14.1.3	06.12.2011	Release Notes for PowerFactory Version 14.1.3
14.1.2	12.08.2011	Release Notes for PowerFactory Version 14.1.2

Table of Contents

1	PowerFactory V14.1.3	1
1.1	Minor Enhancements/Fixes	1
1.1.1	Load Flow/Optimization/Network Reduction	1
1.1.2	Contingency Analysis	3
1.1.3	Short-circuit	4
1.1.4	Simulation/Modal Analysis	5
1.1.5	Reliability Assessment	6
1.1.6	Protection Models	6
1.1.7	Single Line Graphic	8
1.1.8	Graphical User Interface / Dialog	10
1.1.9	Merge Tool	11
1.1.10	DPL	11
1.1.11	Reports.....	11
1.1.12	Converter / Import / Export / DGS / Engine	12
1.1.13	Miscellaneous	13
2	PowerFactory V14.1.2	16
2.1	Minor Enhancements/Fixes	16
2.1.1	Load Flow	16
2.1.2	Contingency Analysis	17
2.1.3	Harmonics	17
2.1.4	Short-circuit	18
2.1.5	Simulation.....	19
2.1.6	Reliability Assessment	20
2.1.7	Protection Models	21
2.1.8	Single Line Graphic	22
2.1.9	Graphical User Interface / Dialog	23
2.1.10	Converter / Import / Export / DGS / Engine	24
2.1.11	DPL.....	25
2.1.12	Miscellaneous	25

1 PowerFactory V14.1.3

1.1 Minor Enhancements/Fixes

1.1.1 Load Flow/Optimization/Network Reduction

Description	Solution Note	ID
Station Controller/SVS: Allow negative droop.	A negative droop can now be entered to handle the Q measurement direction.	#7072
Station Controller: Load flow calculation fails if two machines are connected on LV side.	Problem solved.	#6654
Station Controller: Load flow outer loop is toggling in special cases when options "Max. Reactive Reserve" and "HV control" are enabled.	Problem solved.	#7069
Station Controller: Load flow calculation fails if the reactive power contribution is zero and the machine controls the local terminal voltage.	Problem solved.	#7027
Station Controller: Droop is ignored if the option "Enabled Droop" is enabled and a reduced switch is selected for the "Q measured at" parameter.	Problem solved.	#7075
Load flow calculation does badly converge if the option "Automatic Tap Adjustment" is enabled for a transformer with a small short-circuit impedance.	Problem solved.	#6975
Load flow calculation fails in certain cases with block structure and power equation.	Problem solved.	#7141

Description	Solution Note	ID
Unbalanced load flow calculation: In special cases loads are wrongly considered as unsupplied.	Problem solved.	#6936
DC/AC Load flow calculation: Loading not correctly calculated for a 2-Winding transformer with explicit neutral connection (ElmTr2n).	Problem solved.	#6856 #7136
Misleading warning message if distributed slack by generation is enabled for DC network	Problem solved. Message improved.	#6841
PowerFactory is crashing when a pure neutral terminal ("N") is marked as "Earthed".	Problem solved.	#6854
Wrong warning message: "Number of parallel lines must be equal to the number of circuits in tower type" for lines containing a line section using a tower type with 2 circuits.	Problem solved.	#7093
PowerFactory crashes when a relay is defined in a cubicle without connected element.	Problem solved.	#6907
The sign of Q (reactive power) is rotated if a cubicle is selected of a reduced breaker connected on a gen-oriented model (e.g. syn. Machine).	Problem solved.	#7048
AC Optimal Power Flow calculation crashes when a PWM converter is in the grid.	Problem solved.	#7092

Description	Solution Note	ID
Network Reduction: The short-circuit equivalent does not match if load flow is calculated with distributed slack and some generators are inside the reduced area.	Problem solved.	#6796
Network Reduction: In special cases Coupling elements (ElmTow) are wrongly deleted after reduction.	Problem solved.	#7157

1.1.2 Contingency Analysis

Description	Solution Note	ID
AC/DC Contingency Analysis - Single Time Phase: Support EvtLod/EvtGen/EvtTap.	The following events are now support for AC/DC contingency analysis (single time phase): - "Load Event" (EvtLod) - "Dispatch Event" (EvtGen) - "Tap Event" (EvtTap)	#6729
Multiple Time Phase Contingency: Comparison of contingencies does not work.	Problem solved.	#6972
Multiply Time Phase Contingency: Trace fails if a busbar is split (e.g. meshed corner).	Problem solved.	#6713
Multiply Time Phase Contingency: After a closing a bus bar coupler, sometimes load flow calculation does not converge.	Problem solved.	#7222
Multiply Time Phase Contingency: Endless loop if several switches in a substation are closed and then opened.	Problem solved.	#6899

Description	Solution Note	ID
Contingency Definition: Erroneous contingency numbering and incorrect behaviour in runtime engine mode.	Problem solved.	#6943

1.1.3 Short-circuit

Description	Solution Note	ID
Unbalanced "complete": Angle of transient currents (bus results) are wrongly rotated by 180 deg (I0', 3I0', I1', I2').	Problem solved.	#6882
DFIG/PWM: Transient current not correct if no. of parallel machines greater than 1 (for Equivalent Synchronous Machine Model).	Problem solved.	#6992 DIG704
The maximum breaking current for breakers is not accurately calculated if the option: "Calculate max. Branch Currents = Busbar Currents" is disabled.	Problem solved.	#7253
PowerFactory crashes when a relay is defined in a cubicle without connected element.	Problem solved.	#6907
Ambiguous error message: Short-circuit at line with length = 0km.	Problem solved. Error message improved.	#6833
Short-circuit with current iteration: For additional outer loop iterations, the last iteration is not displayed.	Problem solved.	#7031 DIG746
DPL function: ComShc::ExecuteRXSweep not working for IEC calculation.	Problem solved.	#7134

1.1.4 Simulation/Modal Analysis

Description	Solution Note	ID
Static Generator: Signals "cosref" and "sinref" are not displayed in "Variable Selection" (IntMon) for unbalanced RMS simulation.	Problem solved.	#6918
EMT Simulation, initialized from unbalanced load flow, not correct for DFIG machine (with two connections).	Problem solved.	#7013
Current Measurement: Current is rotated if defined in a cubicle of a reduced breaker connected on a gen-oriented model (e.g. syn. Machine).	Problem solved.	#7048
"Result Folder" and "Event List" are not automatically assigned when starting the simulation with the "Start Simulation ..." button.	Problem solved.	#7096
ElmFile reading ComTrade: Wrong interpolation if oversampling is applied.	Problem solved.	#6826 DIG637
Modal Analysis: Performance optimization for report.	Performance improved for reports.	#7080

1.1.5 Reliability Assessment

Description	Solution Note	ID
Too many switches are closed after executing substation automation.	Problem solved.	#6974
Maintenance events depend on previous run of calculation.	Problem solved.	#6723

1.1.6 Protection Models

Description	Solution Note	ID
Context Menu: "Show" -> "Rx-Plot" on Sub-relay corrupts relay model.	Problem solved.	#6526 #7086
Distance polygonal unit: Sometimes simulation hangs after relay is tripping.	Problem solved.	#7131
Polarizing Unit: "Assume k0" is not correctly working if earth factor representation is "Z0/Z1" or "(Z0-Z1)/Z1".	Problem solved.	#7003
Polarizing Unit: Earth factor representation should be displayed.	The "Earth factor representation" is now displayed the polarizing unit.	#7063
Time Overcurrent unit: "Reset delay" does not work when the reset time multiplier is set to 0.	Problem solved.	#6735 #6967
Characteristic is not correctly displayed when the "Min Trip/Max clear Time Overcurrent" usage is set (TypChatoc).	Problem solved	#7054
Mho unit: Does not manage correctly the "External" and the "Reverse external" direction.	Problem solved.	#7058

Description	Solution Note	ID
Single phase CT adapter block: The output signals for the real and imaginary part are not correctly calculated.	Problem solved.	#7181
Distance Polygonal unit: Used for "GE UR" devices does not trip when set non directional.	Problem solved.	#7056
SEL 311: 51N unit set as directional element looking at the forward direction trips for a reverse fault.	Problem solved.	#7060
Power Swing unit: Number of crossings are not correctly counted.	Problem solved.	#6998
The Siemens 7UM62x relay model does not trip during an Out-Of-Step simulation when the number of crossing is greater than 1.	Problem solved.	#6962 DIG505
ABB Polygonal Unit (670): Impedance calculation for earth faults is not correct. A wrong earth compensation factor is used.	Problem solved.	#7238
Distance Blinder unit: Dialog does not show the "R range" for the "Neg. resistive Blinder".	Problem solved.	#6958
Power Swing unit: Dialog shows the blocking configuration option even when the blocking is not available.	Problem solved.	#6960
Recloser unit: "logic" tab page loses all lines except the first one when a simulation is initialized.	Problem solved.	#7014
A discrete range for an integer variable is not correctly working. Object always modified when opening the dialog.	Problem solved.	#7084

1.1.7 Single Line Graphic

Description	Solution Note	ID
<p>Improvements: Colouring according to results of Contingency Analysis.</p>	<p>Improvements:</p> <p>For alarm mode "Voltage violation / Overloading":</p> <ul style="list-style-type: none"> - Colour overloadings according variables "maxLoading"/"maxLoading_st" and voltage violations according to "max_v"/"min_v". <p>For other mode "Low and High Voltage / Loading":</p> <ul style="list-style-type: none"> - Colour loadings of branch elements according variables "maxLoading"/"maxLoading_st" and voltages according to "min_v"/"max_v". <p>Beachballs colouring according to max. voltage deviation from base case when two colours are used in mode "Low and High Voltage / Loading".</p> <p>Beachballs colouring according to max. absolute voltage violation when two colours are used in mode "Voltage violation/Overloading".</p>	#7044
<p>Boundary colouring for composite objects.</p>	<p>Boundary colouring improved.</p>	#6846
<p>Area and Zone colouring for composite objects using more than one colour</p>	<p>Area/Zone colouring improved.</p>	#6913
<p>Performance Optimization: Opening a SGL-diagram containing many graphical composite nodes takes a very long time.</p>	<p>Performance improved.</p>	#6845
<p>Redrawing more than one branch object at the same time not working properly.</p>	<p>Problem solved.</p>	#7039
<p>Missing info message when bay ends are already occupied in other variation.</p>	<p>Problem solved.</p>	#6699

Description	Solution Note	ID
Changing peg points of rectangle not working properly.	Problem solved.	#7082
"Apply to all graphics" for layers shall only consider visibility.	Problem solved.	#7047
Exporting diagram as WMF does not show logo in title if zoomed in.	Problem solved.	#7040
WMF export leads in special cases to incorrectly displayed background graphic.	Problem solved.	#6755
Alignment of local text boxes not working.	Problem solved.	#7107
Lines not ending exactly on a drawn node lose in special cases their graphical connections.	Problem solved.	#7229
In special cases the connecting to substation in simplified view is not working correctly.	Problem solved.	#7230
Colouring according "Voltage Levels": The transformer symbol is in special cases only shown half.	Problem solved.	#7231
Split and joined lines are not considered in permanent Diagrams.	Problem solved.	#7232

1.1.8 Graphical User Interface / Dialog

Description	Solution Note	ID
PowerFactory is in special cases not responding when element context menu should pop-up.	Problem solved.	#6997 #6839 #7225
Characteristic cannot be defined for rating object (IntThrating) e.g. for seasonal ratings	Problem solved.	#6876
Lines/Transformers/Series Reactor: Max. Loading parameter is not displayed in the Data Manager at load flow page.	Problem solved.	#6887
Station Controller: Wrong voltage setpoint is displayed when pressing "info" button and "Enable Droop" and "bus target voltage" option is enabled.	Problem solved.	#7067
Switching Rule for Substations: Only open switches are collected as default switches.	Problem solved.	#6984
PowerFactory is crashing when filtering (SetFilt) according to "*.IntRef" and empty references exists.	Problem solved.	#6808
PFD export dialog: Disabling "Export to former version" does not work.	Problem solved.	#6923
Content of block diagram is not shown if no project is active.	Problem solved.	#6719
Branch (ElmBranch): "Tie Off" detection not correct for special cases.	Problem solved.	#7204

Description	Solution Note	ID
Data Manager: For "Common Impedance" are wrong column names displayed for transient/sub-transient impedances.	Problem solved.	#7220

1.1.9 Merge Tool

Description	Solution Note	ID
Hidden objects are not correctly merged.	Problem solved.	#6462
Source project corrupted by deletion of copied data.	Problem solved.	#6836
Name changes of objects in variations are ignored.	A warning message about ignored hidden objects is printed to the output window.	#6862

1.1.10 DPL

Description	Solution Note	ID
"SetVal" function not working for integer attributes.	Problem solved.	#6821

1.1.11 Reports

Description	Solution Note	ID
Unhandled exception caused by contingency report (ComCntreport).	Problem solved.	#6955

Description	Solution Note	ID
ASCII Result File Export: Header should use the element name like the subplots.	Problem solved.	#6817

1.1.12 Converter / Import / Export / DGS / Engine

Description	Solution Note	ID
DGS: Import of load data 'operating point' fails for mode 'I, cos(phi)'.	Problem solved.	#6753
DGS 5.0 Import: - Pointers from EditObject to graphics objects are not set. - Crash if HiddenObject table contains invalid references. - Object with alternative input modes for attributes e.g. Shunt (ElmShunt) are in special cases not correctly imported.	Problems solved.	#6814 #6996 #7210
Successive DGS imports gradually getting slower.	Problems solved.	#6811
API: Engine mode lost after API destruction.	Problem solved.	#7077
PSS/E export: "Use Characteristic Names" leads to a PowerFactory crash.	Problem solved.	#6725
PSS/E import is crashing when the "Name" of the "bus data" is longer than 12 characters.	Problem solved.	#6881

Description	Solution Note	ID
DVG Import improvements ...	Improvements: - Modified structure by adding Sites and Substations - Support of Shunts and NEC/NER elements - Various minor fixes	#7266
CIM: ENTSO-E 2009 Export: - EquipmentContainer handling improvements - various problems	Problems solved.	#7119 #7130
CIM: ENTSO-E 2009 Import: - Several RegulatingObjects controlling same busbar. - various problems	Problem solved.	#7128 #7165 #7174

1.1.13 Miscellaneous

Description	Solution Note	ID
OPC link needs to be supported for 64bit PowerFactory version.	OPC link for 64bit PowerFactory version now supported.	#7155
Data Verification: Modifies input parameters if characteristics are present.	Problem solved.	#7226
German online help.	The German online help is now available.	#7185
Automatic check/repair mechanism required when user settings are corrupted.	Problem solved.	#6790
PFD import into SQL Server Database fails in a special case.	Problem solved.	#6706
SQL Server: Missing entries in reference list (Context menu "Output" -> "Reference List").	Problem solved.	#6851

Description	Solution Note	ID
Consider project purge time for minimum version creation time.	Problem solved.	#6823
DPL Library: "Stochastic Switching"	New DPL script for "Stochastic Switching" analysis for EMT simulations available.	#7194
DPL Library: "Impedance Loci"	New DPL script. It supports the definition of R-X loci for the harmonic calculation.	#7195
Template Library improvements.	<p>"DFIG" templates:</p> <ul style="list-style-type: none"> - Voltage correction for the 2-W. Transformer Type - Model improvements: <ul style="list-style-type: none"> + Speed could now flexible initialized + Power ramp after fault now possible <p>"FullyRatedConverterWTG" templates:</p> <ul style="list-style-type: none"> - Generator is now the "main" slot. - Voltage before fault is now flexible (PT1 tracking) or optional constant. <p>"PhotovoltaicSystem_0.4kV_0.5MVA" template:</p> <ul style="list-style-type: none"> - Converter (ElmGenstat) is now main slot. - Description in model adjusted. - i_EEG activates now correct mode. <p>"VariableRotorResistanceWTG_0.69kV_0.66MW" template:</p> <ul style="list-style-type: none"> - Type rotor resistance adjusted to value from controller. - A-stable option activated for all models. - Generator is now the main slot. 	#7216
Library: Standard Macro (1+ssT3)_(1+sT1+ssT2) is not correct.	Macro improved.	#7170
PowerFactory API: Should not reset calculation if calculation irrelevant attribute was changed.	Problem solved.	#7190
PowerFactory is in special cases crashing when running "Flicker Meter" calculation.	Problem solved.	#6849

Description	Solution Note	ID
License Server v14.1 fails to record number of checked out floating licenses in log file.	Problem solved.	#6787
Compatibility issue during setup under Vista/Windows.	Problem solved.	#6477

2 PowerFactory V14.1.2

2.1 Minor Enhancements/Fixes

2.1.1 Load Flow

Description	Solution Note	ID
Wrong "Reactive Power Limit Exceeded ..." output messages after load flow for machines using voltage dependent limit curves.	Problem solved.	#6492
Station Controller: Load flow with enabled option "No Initialisation" fails for Static Generators and DFIG Asynchronous Machine.	Problem solved.	#6509
DC load flow: Wind Zone Scaling Factor not considered for DFIG Machines (ElmAsmsc).	Problem solved.	#6536
Shunt: Current through Capacitor not correctly calculated for unbalance load flow.	Problem solved.	#6499
Station/Tap Controller: Non-deterministic load flow results if the voltage priority is equal.	Problem solved.	#6493

2.1.2 Contingency Analysis

Description	Solution Note	ID
Parallel Contingency: Intelligent time out check.	Improved alive checks for slave processes.	#6481
Multiple time phases: Toggle between AC/DC load flow settings erroneously blocked.	Blocking of AC/DC selection removed.	#6429
AC Contingency Analysis: Voltage Step Change should be voltage deviation from base case in per unit.	Problem solved.	#6438
DC Contingency Analysis: Huge loading if both a line and its branch (ElmBranch) are defined in interrupted table.	Problem solved.	#6602 DIG515
DC Contingency Analysis (Optimized Method): Huge loading if PWM converter controls remote flow.	Problem solved.	#6635 DIG578
Multiple time phases: No Detailed output possible.	Problem solved.	#6551

2.1.3 Harmonics

Description	Solution Note	ID
Shunt: Current through Capacitor not correctly calculated for unbalanced harmonics load flow (with and without IEC sources)	Problem solved.	#6660 #6499
TIF factors for balanced calculation are incorrect (orders 5,11,17,...)	Problem solved.	#6506

Description	Solution Note	ID
DFIG (ElmAsm): Harmonic Model "Impedance" required.	Additional option for the harmonic model of DFIG machines: "Impedance" The "Impedance" option is compatible to V14.0.	#6681
Incorrect HD and THD for edge elements if option "Based on rated voltage/current" is enabled.	Problem solved.	#6672 DIG583
The filter result report is not correct if the output frequency is not the fundamental frequency e.g. 250Hz.	Problem solved.	#6501
Calculation of flicker in unbalanced case incorrect.	Problem solved.	#6684
For harmonic flicker calculation, all DFIG models should always be modelled as current source in the positive sequence system.	Problem solved.	#6687

2.1.4 Short-circuit

Description	Solution Note	ID
Shunt: Current through capacitor not correctly calculated for unbalance short-circuit calculation.	Problem solved.	#6499
Tower/Lines: Short-circuit without load flow initialisation fails if $z0 = 0$	Problem solved.	#6519
Option: "Current Iteration" => "du" not correctly calculated.	Problem solved. The voltage drop is now calculated as follow: $du = u(\text{pre-fault}) - u $	#6469
Short-circuit at a branch fails location is set to 100%.	Problem solved.	#6569 DIG572

Description	Solution Note	ID
Edge element result: m:BrkIpload, m:BrkIbload results are in special cases not available (=0).	Problem solved.	#6647

2.1.5 Simulation

Description	Solution Note	ID
PWM Converter (ElmVsc/ElmVscmono) blocking mode for RMS model.	<p>A new input signal is available to block the PWM converter to switch from a controlled IGBT to a non switched rectifier diode model.</p> <p>The blocking mode can be switched on:</p> <ul style="list-style-type: none"> - per parameter event (EvtParam): "Name of Variable" = "block" - per DSL if the "block" input signal is connected. block = 1 => block (Diode Mode) block = 0 => release blocking <p>In addition, for the RMS simulation the cell capacitor can now be entered in the dialog.</p>	#6628
Unbalanced RMS Simulation: The output signal "fe" of the Voltage Measurement (StaVmea) is not correctly initialized from an unbalanced load flow.	Problem solved.	#6475
Shunt Controller: Model cannot be initialized for unbalanced RMS simulation.	Problem solved.	#6678 DIG528
DFIG (ElmAsm): The rotor currents (Ird, Irq and Ira/b/c) are #INF or #IND.	Problem solved.	#6512
Short-circuit (with short-circuit event) on a branch (ElmBranch) cannot be cleared.	Problem solved.	#6658

Description	Solution Note	ID
RMS Simulation: The DSL "lim()" function is in special cases not correctly working if "Automatic Step Size Adaption" is enabled.	Problem solved.	#6494
Improvements for PQ/I/CT ... measurement initialization.	The output signals of PQ/I measurement (StaPqmea/StaImea) and CT (StaCt) are now always initialized.	#6648
Results not correct if recording e.g. the current of a non-detailed switch.	Problem solved.	#6691

2.1.6 Reliability Assessment

Description	Solution Note	ID
Colouring of feeders incorrect after calculation.	Problem solved.	#6609
Reliability trace does not correctly reflect the maintenance events.	Problem solved.	#6610
Common Mode Failure is calculated as ideal (frequency and duration are 0.0)	Problem solved.	#6631

2.1.7 Protection Models

Description	Solution Note	ID
Current transformer (StaCt) on breaker measures an incorrect currents (=0).	Problem solved.	#6472
Fuses, stored inside a cubicle are not correctly considered if the breaker reduction mode is set to "enhanced".	Problem solved.	#6473 DIG535
Overcurrent Unit: Breakers in detailed substation are not correctly identified for the "Total Clear Curve" definition.	Problem solved.	#6537
Relay Logic: PowerFactory is crashing when running load flow/short-circuit if an additional switch is selected in the "Open" table.	Problem solved.	#6591
Time-Overcurrent Unit (RelToc): "Reset delay" does not work when the reset characteristic is an ANSI/IEEE equation.	Problem solved.	#6524
The negative sequence current (I2) value is not calculated properly running an EMT simulation if the DFT filter is enabled.	Problem solved.	#6525
The relay differential block must be improved to support different ways to define the harmonic blocking and to allow a delayed trip with inverse characteristic	Problem solved.	#6531
R-X-Diagram: Number of parallel transformers is not considered when drawing transformer impedance.	Problem solved.	#7249

2.1.8 Single Line Graphic

Description	Solution Note	ID
In special cases PowerFactory is crashing when activating a variation.	Problem solved	#6530
WMF export/printing: - leads to incorrectly displayed company logo. - Picture does not correspond to given angle e.g. the picture is rotated by 90 deg.	Problems solved.	#6589 #6669
De-energized colouring: For branches (ElmBranch) containing switches (StaSwitch) or CT's (StaCt), Relays ... the branch always shown as de-energized.	Problem solved.	#6676
Copy-> Paste of a line leads to missing graphical connections if it connects two substations.	Problem solved.	#6664
Cubicle connection lost after connecting a load at a substation and no bay is free.	Problem solved.	#6693 DIG604
Mark in Graphic is not marking the line end if connected to beach ball.	Problem solved.	#6557
Context Menu: "Define" -> "Zone/Area/Owner/Operator" can take a very long time if executed from diagram.	Performance improved.	#6571 DIG524
Branch (ElmBranch): Wrong result box is displayed (e.g. loading was displayed from first/last connected line instead of the branch).	Problem solved.	#6651
Inserting a template and connecting into substation is not correctly working.	Problem solved.	#6665

Description	Solution Note	ID
In "Draw existing net elements" the logical switch icon should list switches of substation drawn in simplified view.	Problem solved.	#6587
Missing description of "Inactive" colour in colour legend if option "1. Energizing Status" is enabled.	Problem solved.	#6544
Improperly drawn connection lines after CIM import	Problem solved.	#6523

2.1.9 Graphical User Interface / Dialog

Description	Solution Note	ID
Virtual Instrument, Curve-Input: Selection of matrix object is not possible.	Problem solved.	#6541
Data Manager context menu: "Characteristic" -> "New Characteristic" -> "Characteristic from File" is not working	Problem solved.	#6543 DIG501
Path colouring is not automatically set when a new path is defined.	Problem solved.	#6595
Capability diagram (ElmSym/ElmGenstat/ElmAsm): wrong x-axis => must be from -1 to 1	Problem solved.	#6594
Virtual Power Plant: Incorrect tables for dispatchable/non-dispatchable machines when using variations.	Problem solved.	#6573

2.1.10 Converter / Import / Export / DGS / Engine

Description	Solution Note	ID
PSS/U import: - Current ratings in line types are not imported. - Single phase lines are not correct connected to the corresponding phase.	Problems solved.	#6503 DIG522 #6585 DIG576
PSS/E export: - Option to use the characteristic name (chr_name) for the branch identifier (CKT/ID)/ bus number, area number, - if a SVS is in station controller the Q distribution is not correctly calculated. - if a generator is a slack controls remotely a busbar => not possible in PSS/e => set to actual local voltage control. -Droop control of SVS/ElmGenstat/ElmAsm(DFIG) not correctly exported. -all generators at the same busbar must have the same control settings (IREG, VS => also PQ machines). - IEEE Controller: Parameter mapping is not correct for "avr_AC8B" model.	New option available "PSS/E Bus Number": - Automatic (bus numbers automatically assigned) - Use Serial Number - Use Characteristic Name Problems solved.	#6605 #6612
Neplan import: Some connection lines are not drawn.	Problem solved.	#6572
CIM ENTSO-E 2009 corrections II	Problem solved	#6415

2.1.11 DPL

Description	Solution Note	ID
ComExit.Execute() crashes PowerFactory.	Problem solved.	#6620
GetControlledNode(bus,...) (ElmSym/ElmGenstat/ElmSvs/ElmAsm(DFIG)) not correctly working for bus=-1	Problem solved.	#6618

2.1.12 Miscellaneous

Description	Solution Note	ID
Calculate results for all breakers: PowerFactory crashes if element with neutral exists.	Problem solved.	#6479 DIG539
Internal topology error if the phase technology of two terminals are differed and are connected with a reduced switch.	Problem solved.	#6482 DIG539
Network Reduction: Extremely slow if option: "Calculate results for all breakers" is enabled.	Problem solved, performance improved.	#6480
Merge Tool: Hidden objects are not correctly merged.	Problem solved.	#6462
Result file export to Comtrade leads to inconsistent files.	Problem solved.	#6632
Cubicle (StaCubic): Syntax: "e:cpCB:0" returns wrong breaker.	Problem solved.	#6515

Description	Solution Note	ID
Data Verification (ComCheck): Check missing when the number of circuits/earth wire have been changed in the tower type and the line coupling is not up-to-date.	Problem solved.	#6533
ComExit=> Execute leads to "connection to license server lost" error message.	Problem solved.	#6613
Improved demo examples for Reliability	The DEMO examples for the Reliability assessment are improved.	#6627
Template Library Improvements	<ul style="list-style-type: none"> - All Templates: Active Power Reduction was not limited, is now limited to 0..1 - All Wind turbine templates are now ready to connect (HV side of transformer). - All DFIG: Active power return of DFIG is now modelled via PT1 behaviour (parameter: Tramp), no jump of active power after fault. - All DFIG: Initialisation improved (xr). - Names of DFIG 2.5MW and Fully rated WTG 2.3 and 5MW corrected. 	#6616
Online help	Online help improved.	#6600
Virtualisation: Hardlock license server available within VMWare virtualized machine.	Problem solved.	#6685